


NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
ROSEMARY LAKE DAM (MA.) (U) CORPS OF ENGINEERS WALTHAM
MA NEW ENGLAND DIV JAN 80

1/1

F/G 13/13

NL

END



NATIONAL BUREAU OF STANDARDS
MICROCOPY RESOLUTION TEST CHART

AD-A155 811

CHARLES RIVER BASIN
NEEDHAM, MASSACHUSETTS

ROSEMARY LAKE DAM
MA 01112

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

*Original contains color
plates and DTIC reproductions
will be in black and
white



DTIC
SELECTED
JUL 03 1985
G

DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
WALTHAM, MASS. 02154

JANUARY 1980

EXEMPT FROM AUTOMATIC DECLASSIFICATION

Approved for public release
Distribution Unlimited

85 06 7 055

DTIC FILE COPY

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER MA 01112	2. GOVT ACCESSION NO. AD-A155811	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Rosemary Lake Dam NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS		8. CONTRACT OR GRANT NUMBER(s)
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE January 1980
		13. NUMBER OF PAGES 45
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		16a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Charles River Basin Needham, Massachusetts Rosemary Brook		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) The dam is an earth embankment about 440 ft. long with a top width of about 50 ft. The dam is small in size with a hazard potential of high. The dam appears to be in fair condition. There are various operation and maintenance measures that the owner should undertake,		



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF
NEDED

MAY 30 1980

Honorable Edward J. King
Governor of the Commonwealth of
Massachusetts
State House
Boston, Massachusetts 02133

Dear Governor King:

Inclosed is a copy of the Rosemary Lake Dam Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Department of Environmental Quality Engineering, the cooperating agency for the Commonwealth of Massachusetts. In addition, a copy of the report has also been furnished the owner, the town of Needham, Massachusetts.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Department of Environmental Quality Engineering for your cooperation in carrying out this program.

Sincerely,

MAX B. SCHEIDER
Colonel, Corps of Engineers
Division Engineer

Incl
As stated

ROSEMARY LAKE DAM

MA 01112

CHARLES RIVER BASIN

NEEDHAM, MASSACHUSETTS

Accession For	
NTIS GRA&I	<input checked="checked" type="checkbox"/>
DTIC TAB	<input checked="checked" type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By _____	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A/	

DTIC
COPY
INSPECTED
1

PHASE I INSPECTION REPORT

NATIONAL DAM INSPECTION PROGRAM

NATIONAL DAM INSPECTION PROGRAM
PHASE I INSPECTION REPORT

Identification No.: MA 01112
Name of Dam: Rosemary Lake Dam
Town: Needham
County and State: Norfolk, Massachusetts
Stream: Rosemary Brook
Date of Inspection: October 16, 1979

BRIEF ASSESSMENT

Rosemary Lake Dam is an earth embankment approximately 440 feet long with a top width of about 50 feet. The upstream face of the dam is a stone parapet wall and the downstream slope of the embankment which is the lawn of an apartment complex is an estimated 20H:1V. The service and auxiliary spillways are both drop-inlet structures which discharge into two 66-inch diameter conduits; however, the conduits are 48-inch diameter at their downstream outlets. The dam once furnished the water needs of a mill located at the damsite; however, the impounded waters are now used for recreational purposes by the Town of Needham.

The lake behind the dam is about 1,100 feet long and has a surface area at the spillway crest level of about 15 acres. The drainage area above the dam is 1.2 sq. miles and the maximum storage at the top of the dam is about 91 acre-feet. The height of the dam is approximately 12 feet; therefore the size classification is "Small." A breach of the dam would have a critical effect on the 210 unit apartment complex built immediately downstream of the dam as well as having an impact on an elementary school 1,700 feet downstream and seven homes 3,700 feet downstream. The dam has been classified as having a "High" hazard potential. Based on the "Small" size and "High" hazard potential, the range for the test flood is one-half of the Probable Maximum Flood (PMF) to the full PMF. The selected test flood for the project is one-half of the PMF based on the dam height, storage capacity and downstream flood impact area.

The dam appears to be in fair condition. The upstream stone parapet wall appears to be aligned properly and there were no signs of depressions, seepage or other deficiencies observed along the crest and downstream slope of the embankment. About 5 gpm seepage was noted entering a storm sewer on the upstream side of the dam along Rosemary Street.

The test flood peak inflow for the facility was computed as 1,020 cfs. The routed test flood outflow is also 1,020 cfs which results in the dam being overtopped


by 0.7 feet. The spillway system can pass 247 cfs or about 24 percent of the routed test flood outflow without overtopping of the dam.

Within one year after receipt of this Phase I Inspection Report, the Owner, the Town of Needham, should retain the services of a qualified registered professional engineer and implement the results of his evaluation of the following: (1) assess further the potential for overtopping and the adequacy of the spillways; (2) study the cause of the seepage to the storm sewer located under Rosemary Street; (3) investigate the seismic stability of the dam.

The Owner should also implement the following operation and maintenance measures: (1) clear obstructions from the channel downstream of the spillway conduits; (2) verify the operability of the low level drain gate valve; (3) repair or replace the grating on the auxiliary spillway inlet structure; (4) develop a formal surveillance and flood warning plan, including round-the-clock monitoring during heavy precipitation; and (5) institute a program of annual technical inspection.

O'BRIEN & GERE ENGINEERS, INC.


John J. Williams
Vice President
New York Registration No. 050794



Date 22 FEB. 80

This Phase I Inspection Report on Rosemary Lake Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.

Carney M. Terzian

CARNEY M. TERZIAN, MEMBER
Design Branch
Engineering Division

Richard J. DiBuono

RICHARD DIBUONO, MEMBER
Water Control Branch
Engineering Division

Aramast Mahtesian

ARAMAST MAHTESIAN, CHAIRMAN
Geotechnical Engineering Branch
Engineering Division

APPROVAL RECOMMENDED:

Joe B. Fryar

JOE B. FRYAR
Chief, Engineering Division

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation: however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

The Phase I Investigation does not include an assessment of the need for fences, gates, no-trespassing signs, repairs to existing fences and railings and other items which may be needed to minimize trespass and provide greater security for the facility and safety to the public. An evaluation of the project for compliance with OSHA rules and regulations is also excluded.

TABLE OF CONTENTS

<u>SECTION</u>	<u>PAGE</u>
Letter of Transmittal	
Brief Assessment	
Review Board Page	
Preface	i
Table of Contents	ii-iv
Overview Photo	v
Location Map	vi

REPORT

1. PROJECT INFORMATION

1.1	General	1-1
	a. Authority	1-1
	b. Purpose of Inspection	1-1
1.2	Description	1-1
	a. Location	1-1
	b. Description of Dam and Appurtenances	1-1
	c. Size Classification	1-2
	d. Hazard Classification	1-2
	e. Ownership	1-3
	f. Operator	1-3
	g. Purpose of Dam	1-3
	h. Design and Construction History	1-3
	i. Normal Operational Procedures	1-3
1.3	Pertinent Data	1-3
	a. Drainage Area	1-3
	b. Discharge at Damsite	1-3
	c. Elevation	1-4
	d. Reservoir	1-4
	e. Storage	1-5
	f. Reservoir Surface	1-5
	g. Dam Data	1-5
	h. Diversion and Regulating Tunnel	1-5
	i. Spillways	1-5
	j. Regulating Outlets	1-6

TABLE OF CONTENTS (Con't)


<u>SECTION</u>	<u>PAGE</u>
2. ENGINEERING DATA	
2.1 Design	2-1
2.2 Construction	2-1
2.3 Operation	2-1
2.4 Evaluation	2-1
a. Availability	2-1
b. Adequacy	2-1
c. Validity	2-1
3. VISUAL INSPECTION	
3.1 Findings	3-1
a. General	3-1
b. Dam	3-1
c. Appurtenant Structures	3-1
d. Reservoir Area	3-1
e. Downstream Channel	3-2
3.2 Evaluation	3-2
4. OPERATIONAL AND MAINTENANCE PROCEDURES	
4.1 Operational Procedures	4-1
a. General	4-1
b. Description of Any Warning System in Effect	4-1
4.2 Maintenance Procedures	4-1
a. General	4-1
b. Operating Facilities	4-1
4.3 Evaluation	4-1
5. EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES	
5.1 General	5-1
5.2 Design Data	5-1
5.3 Experience Data	5-1
5.4 Test Flood Analysis	5-1
5.5 Dam Failure Analysis	5-2

TABLE OF CONTENTS (Con't)

<u>SECTION</u>	<u>PAGE</u>
6. EVALUATION OF STRUCTURAL STABILITY	
6.1 Visual Observation	6-1
6.2 Design and Construction Data	6-1
6.3 Post-Construction Changes	6-1
6.4 Seismic Stability	6-1
7. ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES	
7.1 Dam Assessment	7-1
a. Condition	7-1
b. Adequacy of Information	7-1
c. Urgency	7-1
7.2 Recommendations	7-1
7.3 Remedial Measures	7-2
a. Operation and Maintenance Procedures	7-2
7.4 Alternatives	7-2

APPENDICES

APPENDIX A - INSPECTION CHECKLIST	A-1 to A-10
APPENDIX B - ENGINEERING DATA	B-1 to B-4
APPENDIX C - PHOTOGRAPHS	C-1 to C-4
APPENDIX D - HYDROLOGIC AND HYDRAULIC COMPUTATIONS	D-1 to D-15
APPENDIX E - INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS	



OVERVIEW OF THE UPSTREAM FACE OF ROSEMARY LAKE DAM. (10/16/79)



OVERVIEW OF THE DOWNSTREAM FACE OF ROSEMARY LAKE DAM. (10/16/79)

SECTION 6

EVALUATION OF STRUCTURAL STABILITY

6.1 Visual Observations

At the time of inspection, the dam showed no visible signs of instability. The stone parapet wall at the upstream face of the dam appears to be sound and there is no significant evidence of pavement deterioration on Rosemary Street. The downstream slope also appears to be in good condition and is well maintained.

6.2 Design and Construction Data

There is no known design and construction data available for the original dam or for any subsequent modifications.

6.3 Post Construction Changes

The only known modifications of the original dam construction consist of the following:

a. Reconstruction of the stone masonry parapet wall along the upstream face of the dam in 1933.

b. Plugging of the inlet to the race serving the former Tillotson Rubber Company (date unknown).

c. Paving and repaving of Rosemary Street on the dam crest (dates unknown).

d. Construction of the apartment complex just to the north of Rosemary Street with subsequent lawn construction which modified the downstream slope of the dam (approximate date, 1974).

e. It appears that the 66-inch diameter outlet conduits from the service and auxiliary spillways were extended with 48-inch diameter reinforced concrete pipe at the same time the apartment complex was constructed.

6.4 Seismic Stability

Rosemary Lake Dam is located in Seismic Zone 3 of the "Seismic Zone Map of Contiguous States." Considering its "High" hazard classification, a seismic stability investigation should be conducted as recommended in Section 7.

The peak inflow and routed outflow for the test flood were both calculated to be 1,020 cfs. The routed test flood outflow corresponds to a stage of 3.4 feet above the service spillway crest and 0.7 feet above the top of the dam. The combined spillway capacity without overtopping the dam was calculated to be 247 cfs which is about 24 percent of the routed test flood outflow.

5.5 Dam Failure Analysis

A failure of the embankment was simulated by the HEC-1-DB computer program assuming a 44-foot wide and 8.7-foot deep breach with vertical side slopes developing within one hour. The failure is assumed to occur with the reservoir surface at the top of dam elevation. The resulting outflow was routed to the 210-unit apartment complex located approximately 150 feet downstream of the dam. The increase in stream depth at this point was computed to be 7.2 feet. About 1,700 feet downstream, in the vicinity of an elementary school, the increase in stream depth is about 5.3 feet and about 3,700 feet downstream, in the vicinity of 7 homes, the increase in stream depth is about 6.6 feet.

SECTION 5

EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES

5.1 General

Rosemary Lake Dam has a watershed about 1.2 miles long and 1.0 miles wide. The drainage area lies almost entirely within the Town of Needham which is developed residentially, commercially and industrially. The topography is hilly ranging from Elev. 250 to Elev. 99 at the damsite. Rosemary Brook approaches the reservoir from the west and south adjacent to the basin divide. The watercourse meanders excessively through the basin.

5.2 Design Data

Neither hydraulic nor hydrologic design data is available for Rosemary Lake Dam.

5.3 Experience Data

No records of high reservoir pools or dam overtoppings are available for this site.

5.4 Test Flood Analysis

Based on the "Small" size and "High" hazard potential, the range for the test flood is one-half of the Probable Maximum Flood (PMF) to the full PMF. The selected test flood is one-half of the PMF based on the relatively small storage capacity and the resistance to breaching due to the extremely flat downstream slope. Hydrologic and hydraulic calculations were performed with the assistance of the HEC-1-DB computer program. The flood hydrographs were constructed from the Snyder unit hydrographs using average coefficients, an initial infiltration of zero, and a constant loss rate of 0.05 inches per hour. The Hop Brook Adjustment Factor was used to reduce the Probable Maximum Precipitation based on the drainage area. Stage vs. Discharge and Stage vs. Storage relationships above the spillway crest were developed for Rosemary Lake Dam. Since both the service and auxiliary spillways discharge into underground conduits, calculations were performed using an orifice equation to approximate the capacity of the two conduits. The results indicate that the discharge capacities of both spillways are orifice controlled for all heads greater than two feet above the spillway crests. The impoundment was assumed to be at the service spillway crest at the beginning of the storm event. Because of the excessive meandering of the watercourse through the basin, the time of travel from the farthest point in the basin is longer than might be expected for a drainage area of this size. Therefore, the lag time is estimated to be about 3 hours for construction of the unit hydrograph.

SECTION 4

OPERATION AND MAINTENANCE PROCEDURES

4.1 Operational Procedures

a. General. The normal operational procedures consist of opening the auxiliary spillway sluice gate during periods of heavy precipitation and/or runoff and draining the lake each year in order to clean the adjacent swimming pool area prior to the start of the swimming season.

b. Description of Any Warning System in Effect. According to the Owner's representative, there is no formal warning system in effect. However, if a situation should arise where there would be a chance of the dam overtopping, the residents of the apartment complex immediately downstream of the dam would be notified by the Town of Needham personnel.

4.2 Maintenance Procedures

a. General. Rosemary Lake is maintained by the Parks and Recreation Department for recreation purposes. Consequently, personnel from that department would be involved in clearing debris from spillway inlets and performing other similar maintenance tasks. In general, however, any maintenance of the dam is performed through the Department of Public Works on an as needed basis.

b. Operating Facilities. Operation of the auxiliary spillway sluice gate is controlled through the office of Mr. Jack Marr, Town Engineer. Mr. Marr's office would be responsible for notifying the Department of Public Works if maintenance work would need to be performed on the gate or other dam facilities.

4.3 Evaluation

For the most part, it appears that the dam is adequately maintained and operated. There is no evidence of overtopping and the existing facilities, including appurtenant structures and downstream drainage ways, appear to be in good condition, except for the grating on the auxiliary spillway inlet structure which needs to be repaired or replaced.

The Owner's representative did not know if the low level gate valve a few feet to the left of the service spillway is operable.

e. Downstream Channel. The two discharge conduits from the service and auxiliary spillways terminate at a headwall approximately 300 feet north of the dam. A rectangular-shaped channel with masonry walls conveys the flow another 150 feet to the north and discharges it into a natural stream bed. The width of the channel varies from 13 feet at the headwall to approximately 9 feet at the point of discharge. The height varies within a range of 4 to 5 feet. The bottom of the discharge channel has a significant amount of debris consisting primarily of stones and tree branches. Approximately 50 feet downstream of the headwall, a single lane concrete bridge has been constructed across the channel. There is a cross-sectional flow area of about 47 square feet under the bridge.

The stream bed downstream of the discharge channel averages about 8 feet in width with 2H:1V side slopes. A small amount of vegetation lines the channel, but does not appear to restrict the flow significantly.

The apartment buildings on the left side of the brook could experience appreciable damage if runoff significantly exceeds the channel capacity.

3.2 Evaluation

The dam appears to be in fair condition. The stone masonry parapet wall is tilted slightly towards the lake and 3 tree stumps were observed along the parapet wall near the left abutment. About 5 gpm of presumed seepage was noted discharging from the Storm sewer on the south side of Rosemary Street.

The grating on the auxiliary spillway inlet structure needs to be repaired or replaced. The size elevation, alignment and operability of the low level drain located a few feet to the left of the service spillway should be verified.

SECTION 3

VISUAL INSPECTION

3.1 Findings

a. General. The field inspection of Rosemary Lake Dam was performed on October 16, 1979. At the time of inspection, the level of the lake was about 2 inches above the crest of the service spillway and approximately 8 inches below the crest of the auxiliary spillway. Underwater areas were not inspected.

Observations and comments made during the field inspection appear on a checklist included as Appendix A of this report.

b. Dam. The dam appears to be in fair condition. The stone masonry parapet wall, rebuilt in 1933, appears to be sound; however, it is tilted slightly towards the lake. In addition, 3 tree stumps were observed along the parapet wall near the left abutment as shown on page 2, Appendix C of this report.

Rosemary Street is located on the top of the dam and appears to be in good condition with only slight longitudinal pavement cracking. It was also noted that there was about 5 gpm of presumed seepage discharging from the storm sewer on the south side of Rosemary Street.

An apartment complex is located just downstream of the dam. In essence, the grassed lawn of the apartment complex forms the downstream slope of the embankment and appears to be very well maintained.

c. Appurtenant Structures. The service and auxiliary spillway inlets appear to be in good structural condition. The only apparent problem is with the bar grating over the auxiliary spillway which is in need of repair or replacement.

It was not possible to adequately assess the condition of the discharge conduits extending from the spillway inlets to the downstream channel. However, the outlets of the pipes are unobstructed and appear to be in good condition.

The valve for a low level drain is located a few feet to the left of the service spillway inlet structure. The size, elevation and alignment of this drain is unknown.

d. Reservoir Area. The slopes along the perimeter of the lake are well vegetated and appear to be stable and free from appreciable erosion. Except for the eastern bank of the lake, the slopes are very gradual.

Further information with regard to the accumulation of silt on the lake bottom was obtained from the Owner and is included in Appendix B of this report.

SECTION 2

ENGINEERING DATA

2.1 Design

No design information relative to the dam construction is available according to Mr. Gary Petrini, Chairman of the Rosemary Lake Reclamation and Building Committee.

2.2 Construction

There is no known information with regard to the construction of Rosemary Lake Dam. The only information available indicates that the stone masonry wall forming the upstream face of the dam was rebuilt in 1933.

2.3 Operation

According to the Town Engineer, Mr. Jack Marr, the sluice gate in the auxiliary spillway inlet chamber is used to draw down the reservoir in anticipation of heavy precipitation and/or runoff. The only other time the sluice gate is operated is when the lake is drained each year to facilitate cleaning of the adjacent swimming pool.

It is not known whether the low level gate valve located immediately to the left of the service spillway is operable.

2.4 Evaluation

a. Availability. All information made available was obtained from personnel of the Town of Needham.

b. Adequacy. Sufficient information was obtained during the field investigation and through conversations and material obtained from the Owner's representative for the purpose of conducting a Phase I dam evaluation.

c. Validity. It appears that the information obtained with regard to the dam's history and the plans obtained from the tax assessor's office are valid.

j. Regulating Outlets.

1. Low level sluice gate inside the auxiliary spillway inlet structure.

Invert Elev.	92.9
Size	2 feet wide by 3 feet high
Description	Sluice gate in upstream wall of auxiliary spillway inlet chamber.
Control Mechanism	Hand wheel

2. Low level drain to the left of the service spillway, the size, elevation and alignment is not known.

e. Storage. (Acre-Feet)

Normal Pool	45
Flood Control Pool	NA
Spillway Crest Pool	45
Top of Dam	91
Test Flood Pool	105

f. Reservoir Surface. (Acres)

Normal Pool	15
Flood Control Pool	NA
Spillway Crest	15
Top of Dam	20
Test Flood Pool	21

g. Dam Data.

Type	Earth embankment
Length	440 feet+
Height	12 feet+
Top Width	50 feet+
Side Slopes	20H:1V (downstream) vertical (upstream)
Zoning	Unknown
Impervious Core	Unknown
Cutoff	Unknown
Grout Curtain	Unknown

h. Diversion and Regulating Tunnel.

Not Applicable

i. Spillways.

Service Spillway

Type	Sharp-crested
Length of Weir	7 feet
Crest Elevation	99.1
Gates	NA
Upstream Channel	None
Downstream Channel	66-inch to 48-inch RCP

Auxiliary Spillway

Type	Sharp-crested
Length of Weir	18 feet
Crest Elevation	99.9
Gates	NA
Upstream Channel	None
Downstream Channel	66-inch to 48-inch RCP

2) Maximum Known Flood. There is no known flood data available for this site.

3) Ungated Spillway Capacity at Top of Dam. The total spillway capacity is restricted to the sum of the capacities through the outlet conduits from the service and auxiliary spillways. Therefore, the total ungated spillway capacity with orifice control is 247 cfs with the reservoir surface at the top of dam Elevation of 101.7.

4) Ungated Spillway Capacity at Test Flood Elevation. The total spillway capacity is restricted to the flow through the outlet conduits. With a test flood Elevation of 102.4, the discharge capacity through the two spillways is estimated to be 330 cfs.

5) Gated Spillway Capacity at Normal Pool Elevation. Not Applicable.

6) Gated Spillway Capacity at Test Flood Elevation. Not applicable.

7) Total Spillway Capacity at Test Flood Elevation. The total spillway capacity with orifice control at test flood Elevation 102.4 is restricted to the capacity of the two discharge conduits, which was computed to be 330 cfs.

8) Total Project Discharge at Top of Dam. (See 3 above)

9) Total Project Discharge at Test Flood Elevation. The combined discharge capacity of the spillways and the flow over the dam at test flood Elevation 102.4, is 1,018 cfs.

c. Elevation. (Feet above NGVD)

Streambed at Toe of Dam	90 +
Bottom of Cutoff	Unknown
Maximum Tailwater	95+
Recreation Pool	99
Full Flood Control Pool	NA
Spillway Crest (Service)	99
(Auxiliary)	99.9
Design Surge (Original Design)	Unknown
Top of Dam	101.7
Test Flood Design Surge	102.4

d. Reservoir Length. (Feet)

Normal Pool	1,100
Flood Control Pool	NA
Spillway Crest Pool	1,100
Top of Dam	1,400
Test Flood Pool	1,500

e. Ownership. The dam is owned by the Town of Needham, Massachusetts. The Town's Parks and Recreation Director, Mr. Richard Foot, is the Owner's representative. He may be contacted at 1471 Highland Avenue, Needham, Massachusetts, 02192, (617-444-5100).

f. Operator. The dam is operated by personnel from the office of the Town Engineer, Mr. Jack Marr, at 470 Dedham Avenue, Needham, Massachusetts, 02192, (617-444-5100, ext. 141).

g. Purpose of Dam. The dam was originally constructed to impound water for the purpose of providing industrial water power. The impoundment is currently used for recreational purposes.

h. Design and Construction History. The design and construction history of the original dam, and for most of the subsequent modifications, is unknown. The only known reconstruction took place in 1933 when the stone masonry wall along the upstream face of the dam was rebuilt. No details of the wall reconstruction have been found.

i. Normal Operational Procedures. The normal operating procedures include:

1) Opening the auxiliary spillway sluice gate during periods of heavy precipitation and/or runoff.

2) Draining the lake each year in order to clean the adjacent swimming pool area prior to the start of the swimming season.

1.3 Pertinent Data

a. Drainage Area. The drainage area above Rosemary Lake Dam is 1.2 square miles. Nearly the entire area is developed for residential, commercial and industrial purposes. The topography is hilly ranging from Elev. 250 to Elev. 99 at the normal pool.

b. Discharge at Damsite.

1) Outlet Works. There are two conduits which convey discharge from Rosemary Lake. One reinforced concrete pipe, which measures 66 inches in diameter at the inlet and 48 inches in diameter at the outlet, extends approximately 300 feet northerly from the service spillway to a rectangular-shaped open channel. With the reservoir surface at the top of dam, the service spillway discharge capacity with orifice control is 92 cfs.

A second conduit extends from the auxiliary spillway to a headwall at the same discharge location as that for the service spillway conduit. It consists of a section of 66-inch diameter pipe which appears to have been extended with an unknown length of 48-inch diameter reinforced concrete pipe. Assuming the same conditions stated for the service spillway outlet, the auxiliary spillway discharge capacity with orifice control would be 155 cfs.

1) The upstream face of the dam consists of a vertical stone masonry wall of unknown depth.

2) The crest of the dam is almost completely covered with asphalt and concrete pavement due to the presence of Rosemary Street and an adjoining sidewalk. The total crest width is approximately 50 feet.

3) The downstream slope of the embankment consists of a gradually sloping grass lawn from the edge of Rosemary Street to an apartment complex.

The service spillway inlet is located approximately 120 feet west of the eastern dam abutment and consists of a 7-foot wide sharp-crested weir. Water overtopping the weir drops approximately 8.5 feet and flows approximately 300 feet in a northerly direction via a reinforced concrete pipe where it discharges into an open channel. The pipe is 66 inches in diameter in the inlet chamber, but is only 48 inches in diameter at the downstream outlet. The downstream channel is discussed in Section 3.1.e of this report.

The auxiliary spillway is located approximately 20 feet east of the main spillway as shown on Plate 1 of Appendix B. This spillway consists of a five-sided structure with a total overflow weir length of eighteen feet. Other features of the auxiliary spillway include:

1) A 2-foot by 3-foot low level sluice gate which may be used to assist in draining the lake.

2) A 36-inch diameter storm sewer draining to the inlet structure from the east. The contributing drainage area is not known.

3) An outlet pipe which extends approximately 300 feet in a northerly direction to an open channel. The pipe is 66 inches in diameter in the inlet chamber, but only 48 inches in diameter at the downstream outlet.

An operator for the low level drain valve is located a few feet to the left of the service spillway. The size, elevation and alignment of this low level drain are unknown.

Further details of the spillway system are shown on pages B-1 and B-2 of Appendix B.

c. Size Classification. Rosemary Lake Dam has a maximum height of approximately 12 feet which places it in the "Small" size category because it is less than 40 feet high. It also falls into the "Small" size category for storage since its maximum storage capacity is about 91 acre-feet which is less than the 1,000 acre-foot upper limit for "Small" size dams. Therefore, Rosemary Lake Dam is in the "Small" size category.

d. Hazard Classification. Because of the presence of a 210-unit apartment complex within 150 feet downstream of the dam, it is likely that a dam failure would result in excessive property damage and probable loss of life. Therefore, the dam is considered a "High" hazard potential structure.

NATIONAL DAM INSPECTION PROGRAM
PHASE I INSPECTION REPORT
ROSEMARY LAKE DAM

SECTION 1

PROJECT INFORMATION

1.1 General

a. Authority. Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of Dam Inspections throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. O'Brien & Gere Engineers, Inc. has been retained by the New England Division to inspect and report on selected dams in the Commonwealth of Massachusetts. Authorization and notice to proceed were issued to O'Brien & Gere Engineers, Inc. by a letter from the Corps of Engineers dated November 6, 1979 and signed by Col. William E. Hodgson, Jr. Contract No. DACW33-80-C-0014 has been assigned by the Corps of Engineers for this work.

b. Purpose of Inspection. The purpose of performing technical inspection and evaluation of non-federal dams is to:


- 1) *Identify conditions which threaten the public safety and thus permit correction in a timely manner by non-federal interests.*
- 2) Encourage and prepare the states to quickly initiate effective dam safety programs for non-federal dams.
- 3) Update, verify, and complete the National Inventory of Dams.

1.2 Description of Project (Information for this dam was obtained from the Town of Needham)

a. Location. Rosemary Lake Dam is located along the northern shore of Rosemary Lake on Rosemary Brook in the Town of Needham, Massachusetts. The dam is shown on the "Newton, Massachusetts" USGS Quadrangle at coordinates N 42° 17.2' and W 71° 14.4'. A regional vicinity map of the Rosemary Lake area has been included as Figure 1, Page vi.

Rosemary Brook outlets into the Charles River approximately 3 miles downstream from Rosemary Lake Dam. The major damage center is a 210-unit apartment complex immediately downstream of the dam.

b. Description of Dam and Appurtenances. Rosemary Lake Dam is an earth embankment approximately 440 feet long with a maximum embankment height of about 12 feet. The dam has the following features:



SECTION 7

ASSESSMENT, RECOMMENDATIONS & PROPOSED REMEDIAL MEASURES

7.1 Dam Assessment

a. Condition. The dam appears to be in fair condition based on the visual inspection of the site on October 16, 1979. The stone masonry parapet wall is tilted slightly towards the lake and 3 tree stumps were observed along the parapet wall near the left abutment. About 5 gpm of presumed seepage was noted discharging from the storm sewer on the south side of Rosemary Street.

The grating on the auxiliary spillway inlet structure needs to be repaired or replaced. The size, elevation, alignment and operability of the low level drain located a few feet to the left of the service spillway should be verified.

The peak inflow and routed outflow rates for the test flood were both calculated to be 1,020 cfs. The routed test flood outflow corresponds to a stage of 3.4 feet above the service spillway and 0.7 feet above the top of the dam. The spillway system is able to pass 247 cfs or about 24 percent of the routed test flood outflow without overtopping of the dam.

A breach of the dam with the water in the lake assumed to be at the top of the dam would result in an increase in stream depth at the apartment complex of 7.2 feet. About 1,700 feet downstream, in the vicinity of an elementary school, the increase in stream depth is about 5.3 feet and about 3,700 feet downstream, in the vicinity of 7 homes, the increase in stream depth is about 6.6 feet.

b. Adequacy of Information. The information made available by the Town combined with that obtained during the field investigation is considered adequate for a Phase I evaluation.

c. Urgency. The recommendations and remedial measures described in this Section should be implemented within one year of receipt of this Phase I Inspection Report.

7.2 Recommendations

Within one year after receipt of this Phase I Report, the Owner, the Town of Needham, should retain the services of a qualified registered professional engineer and implement the results of his evaluation of the following:

- 1) Assess further the potential for overtopping and the adequacy of the spillways.
- 2) Study the cause of the seepage to the storm sewer located under Rosemary Street.

- 3) Investigate the seismic stability of the dam.

7.3 Remedial Measures

a. Operation and Maintenance Procedures. The Owner should also implement the following operation and maintenance measures:

1. Clear obstructions from the channel downstream of the spillway conduits.
2. Verify the operability of the low level drain gate valve.
3. Repair or replace the grating on the auxiliary spillway inlet structure.
4. Develop a formal surveillance and flood warning plan, including round-the-clock monitoring during heavy precipitation.
5. Institute a program of annual technical inspection.

7.4 Alternatives

No valid alternatives to the recommendations described above are considered feasible for this dam.

APPENDIX A

INSPECTION CHECKLIST

VISUAL INSPECTION CHECK LIST
INSPECTION TEAM ORGANIZATION

Project: Rosemary Lake Dam
National I.D. #: MA 01112
Location: Needham, Ma.
Type of Dam: Earth Embankment
Inspection Date(s): October 16, 1979
Weather: Clear, Cool
Pool Elevation: _____ MSL

Inspection Team

Leonard Beck	O'Brien & Gere	Structures
Steve Snider	O'Brien & Gere	Foundations & Materials
Al Hanscom	O'Brien & Gere	Structures
Rod Georges	Bryant & Associates	Hydrology/Hydraulics

*Mr. John J. Williams, Vice-President, O'Brien & Gere has visited the site but not necessarily in conjunction with the inspection team.

Owner's Representative

Mr. Richard Foot ; Parks & Recreation
Director ; Needham, Ma.

VISUAL INSPECTION CHECK LIST

Project: Rosemary Lake Dam

National I.D. #: MA 01112

Date(s): October 16, 1979

AREA EVALUATED	CONDITIONS
<u>DAM EMBANKMENT (Con't)</u>	
Unusual Movement or Cracking at or near Toes	<i>None observed</i>
Unusual Embankment or Downstream Seepage	<i>Seepage to storm sewer located along crest.</i>
Piping or Boils	<i>None observed</i>
Foundation Drainage Features	<i>NA</i>
Toe Drains	<i>NA</i>
Instrumentation System	<i>NA</i>

VISUAL INSPECTION CHECK LIST

Project: Rosemary Lake Dam

National I.D. #: MA 01112

Date(s): October 16, 1979

AREA EVALUATED	CONDITIONS
<u>OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS - SERVICE SPILLWAY</u>	
a. Approach Channel	
General Condition	<i>Unknown, Submerged</i>
Loose Rock Overhanging Channel	<i>None</i>
Trees Overhanging Channel	<i>None</i>
Floor of Approach Channel	<i>Unknown, Submerged</i>
b. Weir and Training Walls	
General Condition of Concrete	<i>Good</i>
Rust or Staining	<i>Corrugated Metal Weir</i>
Spalling	<i>Slight</i>
Any Visible Reinforcing	<i>None</i>
Any Seepage or Efflorescence	<i>None observed</i>
Drain Holes	<i>None observed</i>
c. Discharge Channel	
General Condition	<i>Good, clear of major size debris.*</i>

*See Note 1, next page.

VISUAL INSPECTION CHECK LIST

Project: Rosemary Lake Dam

National I.D. #: MA 01112

Date(s): October 16, 1979

AREA EVALUATED	CONDITIONS
OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS - SERVICE SPILLWAY (Con't)	
Loose Rock Overhanging Channel	<i>Insignificant</i>
Trees Overhanging Channel	<i>Few</i>
Floor of Channel	<i>Rough, much debris</i>
Other Obstructions	<i>Concrete channel width narrows downstream</i>
<u>Misc. Notes :</u> 1.) Discharge over weir flows ~ 150 feet via a 66-inch to 48-inch culvert to rectangular shaped concrete channel. 2.) Suspected that 72-inch dia culvert was extended with 48-inch dia. RCP.	

VISUAL INSPECTION CHECK LIST

Project: Rosemary Lake Dam

National I.D. #: MA 01112

Date(s): October 16, 1979

AREA EVALUATED	CONDITIONS
<p>OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS - <u>AUX.</u> <u>SPILLWAY</u></p> <p>a. Approach Channel</p> <p>General Condition</p> <p>Loose Rock Overhanging Channel</p> <p>Trees Overhanging Channel</p> <p>Floor of Approach Channel</p> <p>b. Weir and Training Walls</p> <p>General Condition of Concrete</p> <p>Rust or Staining</p> <p>Spalling</p> <p>Any Visible Reinforcing</p> <p>Any Seepage or Efflorescence</p> <p>Drain Holes</p> <p>c. Discharge Channel</p> <p>General Condition</p>	<p><i>Unknown, Submerged</i></p> <p><i>None</i></p> <p><i>None</i></p> <p><i>Unknown, Submerged</i></p> <p><i>Very Good</i></p> <p><i>Grating over drop inlet is rusted.</i></p> <p><i>Slight</i></p> <p><i>None</i></p> <p><i>Leakage @ Sluice Gate</i></p> <p><i>NA</i></p> <p><i>66-inch to 48-inch dia. conduit - condition unknown. Channel condition is good.</i></p>

VISUAL INSPECTION CHECK LIST

Project: Rosemary Lake Dam

National I.D. #: MA 5112

Date(s): October 16, 1979

AREA EVALUATED	CONDITIONS
<p>OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS - AUX.</p>	
<p><u>SPILLWAY</u> (Con't)</p>	
<p>Loose Rock Overhanging Channel</p>	<p><i>Insignificant</i></p>
<p>Trees Overhanging Channel</p>	<p><i>Few</i></p>
<p>Floor of Channel</p>	<p><i>Rough, much debris</i></p>
<p>Other Obstructions</p>	<p><i>Concrete channel width narrows downstream</i></p>

VISUAL INSPECTION CHECK LIST

Project: Rosemary Lake Dam

National I.D. #: MA 01112

Date(s): October 16, 1979

AREA EVALUATED	CONDITIONS
<u>OUTLET WORKS - INTAKE CHANNEL AND</u> <u>INTAKE STRUCTURE - SERVICE SPILLWAY</u>	
a. Approach Channel	
Slope Conditions	<i>Unknown, Submerged</i>
Bottom Conditions	<i>Unknown, Submerged</i>
Rock Slides or Falls	<i>None</i>
Log Boom	<i>NA</i>
Debris	<i>Negligible</i>
Condition of Concrete Lining	<i>NA</i>
Drains or Weep Holes	<i>NA</i>
b. Intake Structure	
Condition of Concrete	<i>Very Good</i>
Stop Logs and Slots	<i>None</i>

VISUAL INSPECTION CHECK LIST

Project: Rosemary Lake Dam

National I.D. #: MA 01112

Date(s): October 16, 1979

AREA EVALUATED	CONDITIONS
<u>OUTLET WORKS - INTAKE CHANNEL AND</u> <u>INTAKE STRUCTURE - AUX. SPILLWAY</u>	
a. Approach Channel	
Slope Conditions	<i>Unknown, Submerged</i>
Bottom Conditions	<i>Unknown, Submerged</i>
Rock Slides or Falls	<i>None, Drop Inlet</i>
Log Boom	<i>NA</i>
Debris	<i>Slight</i>
Condition of Concrete Lining	<i>NA</i>
Drains or Weep Holes	<i>NA</i>
b. Intake Structure	
Condition of Concrete	<i>Very Good</i>
Stop Logs and Slots	<i>NA</i>

VISUAL INSPECTION CHECK LIST

Project: Rosemary Lake Dam

ational I.D. #: MA 01112

Date(s): October 16, 1979

AREA EVALUATED	CONDITIONS
<u>OUTLET WORKS - OUTLET STRUCTURE AND OUTLET CHANNEL</u>	
General Condition of Concrete	Outlet conduit condition unknown. Channel good.
Rust or Staining	NA
Spalling	Slight
Erosion or Cavitation	None observed
Visible Reinforcing	None
Any Seepage or Efflorescence	None observed
Condition at Joints	Unknown
Drain Holes	None observed
Channel (d/s of concrete chan.)	Meandering, clear of major size debris
Loose Rock or Trees Overhanging Channel	Several trees
Condition of Discharge Channel	Fair

VISUAL INSPECTION CHECK LIST

Project: Rosemary Lake Dam

tional I.D. #: MA 01112

Date(s): October 16, 1979

AREA EVALUATED	CONDITIONS
<u>INLET WORKS - TRANSITION AND CONDUIT</u>	
General Condition of Concrete	Good @ overflow - condition of RCP unknown.
Rust or Staining on Concrete	Slight
Spalling	Slight
Erosion or Cavitation	None observed
Cracking	None observed
Alignment of Monoliths	NA
Alignment of Joints	Unknown
Numbering of Monoliths	NA

APPENDIX B
ENGINEERING DATA

APPENDIX D

HYDROLOGIC AND HYDRAULIC COMPUTATIONS



7. CHANNEL ABOUT 2000 FEET DOWNSTREAM OF THE DAM WITH HILLSIDE
ELEMENTARY SCHOOL IN THE BACKGROUND LOOKING DOWNSTREAM. (10/16/79)



8. CHANNEL ABOUT 4000 FEET DOWNSTREAM OF THE DAM AT CENTRAL AVE.
(10/16/79)



5. DOWNSTREAM CHANNEL ABOUT 500 FEET DOWNSTREAM OF THE DAM LOOKING UPSTREAM (10/16/79)




6. SEWERAGE PUMPING STATION ABOUT 2000 FEET DOWNSTREAM OF THE DAM ON THE LEFT BANK. (10/16/79)




3. UPSTREAM FACE OF THE DAM SHOWING CUT OFF TREES IN THE FOREGROUND. (10/16/79)




4. UPSTREAM FACE OF THE DAM SHOWING THE AUXILARY SPILLWAY IN THE FOREGROUND AND THE PRIMARY SPILLWAY IN THE BACKGROUND. (10/16/79)




1. MUNICIPAL SWIMMING POOL BUILT IMMEDIATELY NEXT TO ROSEMARY LAKE AT THE LEFT ABUTMENT. (10/16/79)



2. UPSTREAM OVERVIEW OF ROSEMARY LAKE. (10/16/79)





U.S. ARMY CORPS OF ENGINEERS
NEW ENGLAND DIVISION

Contract No DACW 33-80-C-0014

ROSEMARY LAKE DAM

SITE PLAN

DATE: JANUARY

SCALE: NONE

CDRIEN GORE



A

ROSEMARY LAKE

W.S.E. 99.2 (M.S.L.)

LEGEND

THE LOCATION WHERE AND THE DIRECTION IN WHICH EACH PHOTOGRAPH WAS TAKEN AND THE NUMBER OF THE PHOTOGRAPH

APPENDIX C
SELECTED PHOTOGRAPHS OF PROJECT

LOCATION PLAN

Site Plan Sketch

Page
No.

A

Regional Plan

B

PHOTOGRAPHS

No.

Page
No.

1. Municipal swimming pool built immediately next to Rosemary Lake at the left abutment.
2. Upstream overview of Rosemary Lake.
3. Upstream face of the dam showing cut off trees in the foreground.
4. Upstream face of the dam showing the auxiliary spillway in the foreground and the primary spillway in the background.
5. Downstream channel about 500 feet downstream of the dam looking upstream.
6. Sewerage pumping station about 2000 feet downstream of the dam on the left bank.
7. Channel about 2000 feet downstream of the dam with Hillside Elementary School in the background looking downstream.
8. Channel about 4000 feet downstream of the dam at Central Ave.

1

1

2

2

3


3

4

4

APPENDIX C


PHOTOGRAPHS



TOWN OF NEEDHAM
ROSEMARY LAKE
CONTOURS
EXISTING HARD BOTTOM


DATE, MAY 79

TOWN ENGINEER




B-3

Note:
All dimensions and elevations
are approximate.



SERVICE SPILLWAY SECTION



AUXILIARY SPILLWAY SECTION

U.S. ARMY CORPS OF ENGINEERS
NEW ENGLAND DIVISION

Contract No. DACW 33-80-C-0014

ROSEMARY LAKE DAM


SPILLWAY SECTIONS



OBRIEN & GORE

DATE: JANUARY 1980
SCALE: NONE

B-2



U.S. ARMY CORPS OF ENGINEERS	
NEW ENGLAND DIVISION	
Contract No. DACW 33-80-C-0014	
ROSEMARY LAKE DAM	
SITE PLAN	
O'BRIEN & GERR	DATE: JANUARY
	SCALE: NONE
	B-1

ROSEMARY LAKE
W.S.E. 99.2 (M.S.L.)

SUBJECT <i>ROSEMARY LAKE DAM</i>	SHEET	BY	DATE	JOB NO
-------------------------------------	-------	----	------	--------

APPENDIX B
ENGINEERING DATA
TABLE of CONTENTS

<i>SITE PLAN</i>	<u>PAGE</u> <i>B-1</i>
<i>SPILLWAY SECTIONS</i>	<i>B-2</i>
<i>CONTOURS OF EXISTING MUD BOTTOM</i>	<i>B-3</i>
<i>CONTOURS OF EXISTING HARD BOTTOM</i>	<i>B-4</i>


SUBJECT	SHEET	BY	DATE	JOB NO
ROSEMARY LAKE DAM				

APPENDIX D

HYDROLOGIC & HYDRAULIC COMPUTATIONS

TABLE OF CONTENTS

	<u>PAGE</u>
REGIONAL VICINITY MAP, FIGURE 1, SHOWING FLOOD IMPACT AREA	D-1
DESCRIPTION OF SPILLWAYS	D-2
T_p COMPUTATIONS & PMP DATA	D-3
STAGE - DISCHARGE COMPUTATIONS	D-4
STAGE - STORAGE COMPUTATIONS	D-4
STAGE - DISCHARGE & STAGE - STORAGE GRAPHS	D-5
DOWNSTREAM CROSS SECTIONS	D-6
HEC-1 DAM SAFETY VERSION, COMPUTER OUTPUT	D-7 to D-10
HEC-1 DAM SAFETY VERSION, BREACH ANALYSIS, COMPUTER OUTPUT	D-11 to D-15




BRYANT ASSOCIATES, INC.
648 Beacon Street
BOSTON, MASSACHUSETTS 02215
(617) 247-1800


JOB NED-COE, ROSEMARY LAKE DAM
SHEET NO D-2 OF
CALCULATED BY RG DATE 10/30/79
CHECKED BY JS DATE 12/5/79
SCALE

ROSEMARY LAKE DAM

DESCRIPTION OF SPILLWAYS



ELEVATION



PLAN

NOTE:

AUXILLIARY SPILLWAY OUTLET
CONDUIT IS 48" IN DIAMETER
@ DOWNSTREAM END

D-2

BRYANT ASSOCIATES, INC.
648 Beacon Street
BOSTON, MASSACHUSETTS 02215
(617) 247-1800

JOB NED-COE, ROSEMARY LAKE DAM
SHEET NO. D-3 OF _____
CALCULATED BY RG DATE 10/30/79
CHECKED BY JS DATE 12/5/79
SCALE _____

ROSEMARY LAKE DAM

DRAINAGE AREA = 1.23 sq Mi

$$C_t = 2.0 \quad C_p = 0.5$$

T_p COMPS.

$L = 2.2$ Miles ; $L_{ca} = 1.5$ Miles

$$T_p = C_t (L \times L_{ca})^{0.3}$$

$$T_p = 2.0 \times (2.2 \times 1.5)^{0.3} \approx \underline{\underline{3.00 \text{ Hours}}}$$

PMP DATA

FROM HMS # 33 THE 24 HOUR 200 sq Mi INDEX RAINFALL
IS 21.5"

Gh % OF INDEX FOR THIS BASIN

	= 111%
	= 124
	= 133

D-3

BRYANT ASSOCIATES, INC.
648 Beacon Street
BOSTON, MASSACHUSETTS 02215
(617) 247-1800

JOB NED-COE, ROSEMARY LAKE DAM

SHEET NO. D-4 OF

CALCULATED BY RG

DATE OCT. 30, 1979

CHECKED BY [Signature]

DATE 12/5/79

ROSEMARY LAKE DAM

SCALE

STAGE DISCHARGE

H=0 @ SPILLWAY CREST (ELEV: 99.04) Q_1

AUX SPILLWAY (ELEV: 99.88) Q_2

C = 2.28 FOR BROAD CRESTED WEIR

C = 0.65 FOR ORIFICE Q_1

C = 0.67 FOR ORIFICE Q_2

FOR H=0 $Q_1 = 0$

Q_1 FOR $0 < H < 1.92$ $Q_1 = 2.8 \times 7 \times H^{3/2}$

FOR $H > 1.92$ $Q_1 = 0.65 \times 13.44 \times \sqrt{2g} (H - 0.96)^{3/2}$ (ORIFICE)

Q_2 FOR $H < 0.84$ $Q_2 = 0$

FOR $0.84 < H < 2.24$ $Q_2 = 3.0 \times P (H - 0.84)^{3/2}$

FOR $H > 2.24$ $Q_2 = 5.37 \times A (H - 0.84)^{3/2}$

$P \approx 15'$

P = WETTED PERIMETER

A = OP. AREA (ORIFICE)

$A \approx 26 \text{ FT}^2$

REFER TO PAGES 12-26 & 12-27, U.S. DOT, FED. HIGHWAY ADMIN.
HYDRAULIC ENG'R. CIRCULAR #12


ELEVATION	H	SERVICE SPILLWAY	AUX SPILLWAY	AVE WIDTH FLOW OVER DAM	TOPOF DAM	E Q
USC & GS	FT.	Q_1 : CFS	Q_2 : CFS		Q_3 : CFS	CFS
99.04	0	0	0		0	0
100.04	1	19.6	3		0	23
101.04	2	71.5	56		0	128
102.04	3	100.1	205	277	155	460
103.04	4	122.2	248	322	1400	1770
104.04	5	140.9	285	349	3500	≈ 3330
105.04	6	157.4	317	378	6460	≈ 6930
106.04	7	172.3	346	405	10250	≈ 10770
107.04	8	186.0	374	450	15550	≈ 16110

STAGE - STORAGE

ELEV.	AREA
90	0
99	15
110	35

STORAGE (Computed by HEC-1 program)
0
45
120 @ ELEV 103.13

D-4



ROSEMARY LAKE DAM
 STAGE VS. STORAGE
 STAGE VS. DISCHARGE

BRYANT ASSOCIATES, INC.
648 Beacon Street
BOSTON, MASSACHUSETTS 02215
(617) 247-1800

JOB NED-COE, ROSEMARY LAKE DAM

SHEET NO. D-6 OF _____

CALCULATED BY RG DATE 10/30/79

CHECKED BY JS DATE 12/5/79

SCALE _____

ROSEMARY LAKE DAM
DOWNSTREAM X SECTIONS

DAM 3-1

OUTLET

150'




DS-2

1500'

DS-3

2000'

5-4



D-6

FLOODS ROUTED THROUGH ROSEMARY LAKE DAM WITHOUT BREACHING

.....
FLOOD HYDROGRAPH PACKAGE (MC-1)
DAM SAFETY VERSION JULY 1974
LAST MODIFICATION 26 FEB 79
.....

INPUT

HYDROLOGIC ANALYSIS OF ROSEMARY LAKE DAM		NATIONAL DAM SAFETY PROGRAM		NEW ENGLAND DIVISION - COMPS OF ENGINEERS	
1	2	3	4	5	6
A	A	300	0	0	0
H	H	5	9	0	0
J	J	1	1	0	0
J1	J1	.05	.1	.3	.5
K	K	ROSEMARY			
K1	K1	1	1	1	1
M	M	1	1	1	1
P	P	0	21.5	124	133
T	T	3.0	0.5	0	.05
W	W	-1.7	-.05		
X	X	1	DAM-1		
K1	K1	1			
Y	Y	1			
Y1	Y1	1			
Y4	Y4	99	100	101	102
Y5	Y5	0	23.0	124	247
Y6	Y6	0	15	35	460
Y7	Y7	0	99	110	1770
Y8	Y8	0	99	110	3930
Y9	Y9	0	99	110	6930
Y10	Y10	0	99	110	10770
Y11	Y11	0	99	110	16110
Y12	Y12	0	99	110	16110
Y13	Y13	0	99	110	16110
Y14	Y14	0	99	110	16110
Y15	Y15	0	99	110	16110
Y16	Y16	0	99	110	16110
Y17	Y17	0	99	110	16110
Y18	Y18	0	99	110	16110
Y19	Y19	0	99	110	16110
Y20	Y20	0	99	110	16110
Y21	Y21	0	99	110	16110
Y22	Y22	0	99	110	16110
Y23	Y23	0	99	110	16110
Y24	Y24	0	99	110	16110
Y25	Y25	0	99	110	16110

PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS

RUNOFF HYDROGRAPH AT
ROUTE HYDROGRAPH TO
END OF NETWORK

DAM SAFETY VERSION JULY 1978
 LAST MODIFICATION 26 FEB 79

RUN DATE 02/11/80.
 TIME 13.12.04.

HYDROLOGIC ANALYSIS OF ROSEMARY LAKE DAM
 NATIONAL DAM SAFETY PROGRAM
 NEW ENGLAND DIVISION - COMPS OF ENGINEERS

JOH SPECIFICATION									
NU	NHR	N4IN	IUAY	IHR	JMIN	METRC	IPLT	IPRT	INSTAN
300	0	10	0	0	0	0	0	-4	0
JOPEP NWT LROPT TRACE									
5 0 0 0									

MULTI-PLAN ANALYSES TO BE PERFORMED

PERCENTAGES → RTIOS= .05 .10 .15 .20 .25 .30 .50 .75 1.00
 OF PAF USED

INFLOW HYDROGRAPH DEVELOPMENT

TEST FLOOD

SUB-AREA RUNOFF COMPUTATION

INFLOW TO ROSEMARY LAKE

ISTAU	ICOMP	IECON	ITAPE	JPLT	JPAT	INAME	ISTAGE	IAUTO
SEMARY	0	0	0	0	0	1	0	0

HYDROGRAPH DATA

INHDG	INHA	SNAP	TRSPA	TRSPC	RATIO	ISNOW	ISAME	LOCAL
1	1.23	0.00	1.23	0.00	0.000	0	1	0

PRECIP DATA

SPFF	PMS	R6	R12	R24	R48	R72	R96
0.00	21.50	111.00	124.00	133.00	0.00	0.00	0.00

TRSPC COMPUTED BY THE PROGRAM IS .800

LOSS DATA

LRPOT	SIRKW	OLTKW	RIOL	ERAIN	SIRKS	RTOK	SIRTL	CNSTL	ALSMX	RTIMP
0	0.00	0.00	1.00	0.00	0.00	1.00	0.00	.05	0.00	0.00

UNIT HYDROGRAPH DATA

TP= 3.00 CP= .50 NTA= 0

SIRIU= -1.70 RECESION DATA
 DPCS= -.05 RTIOR= 2.00

UNIT HYDROGRAPH END-OF-PERIOD ORIGINATES. LAG= 2.99 HOURS. CP= .50 VOL= .98

2.	6.	13.	21.	30.	40.	51.	62.	73.	85.
97.	107.	115.	123.	129.	133.	136.	137.	136.	132.
126.	121.	116.	112.	107.	103.	99.	95.	91.	87.
84.	80.	77.	74.	71.	68.	65.	63.	60.	58.
55.	53.	51.	49.	47.	45.	43.	42.	40.	38.

SUM 22.44 21.44 1.20 10124
(541.)(551.)(30.)(2846.)

.....

.....

.....

.....

.....

HYDROGRAPH ROUTING

ROUTED OUTFLOW OF ROSEMARY LAKE

ISTAU	ICOMP	IECON	ITAPE	JPLT	JPMT	ISAME	ISTAGE	IAUTO
DAM-I	1	0	0	0	0	1	0	0
GLUSS	CLUSS	AVG	IMES	ISAME	IOPT	IMP	LSTM	
0.0	0.000	0.00	1	1	0	0	0	

MSIPS	NSIDL	LAG	AMSKK	X	TSK	STORA	ISPRAT
1	0	0	0.000	0.000	0.000	-99.	-1

STAGE	99.00	100.00	101.00	101.70	102.00	103.00	104.00	105.00	106.00	107.00
FLOW	0.00	23.00	128.00	247.00	460.00	1770.00	3430.00	6930.00	10770.00	14110.00

SURFACE AREA=	0.	15.	35.
CAPACITY=	0.	45.	312.
ELEVATION=	90.	99.	110.

STAGE-STORAGE DATA

SPILLWAY CREST ELEVATION → 99.0 CHNL SP210 CUOW FXPW ELEV COOL CAKEA FAPL

DAM DATA
LOPEL COOO EXGO DAMWJU
101.7 0.0 0.0 0.

TOP OF DAM ELEVATION → 101.7

- .05 PMF → PEAK OUTFLOW IS 74. AT TIME 20.83 HOURS
- .10 PMF → PEAK OUTFLOW IS 171. AT TIME 20.17 HOURS
- .15 PMF → PEAK OUTFLOW IS 284. AT TIME 19.50 HOURS
- .20 PMF → PEAK OUTFLOW IS 401. AT TIME 19.00 HOURS
- .25 PMF → PEAK OUTFLOW IS 509. AT TIME 18.83 HOURS

ROUTED OUTFLOWS

- .30 PMF → PEAK OUTFLOW IS 611. AT TIME 18.83 HOURS
- .50 PMF → PEAK OUTFLOW IS 1018. AT TIME 18.83 HOURS
- .75 PMF → PEAK OUTFLOW IS 1526. AT TIME 18.83 HOURS
- 1.0 PMF → PEAK OUTFLOW IS 2041. AT TIME 18.67 HOURS

TEST FLOOD → .50 PMF

FLows IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIO 1	RATIO 2	RATIO 3	RATIO 4	RATIO 5	RATIO 6	RATIO 7	RATIO 8	RATIO 9
HYDROGRAPH AT SEMARY ROUTED TO	1.23	3.19	1	102.	204.	307.	409.	511.	613.	1022.	1533.	2044.
	3.19	3.19	1	2.89	5.79	8.68	11.58	14.47	17.37	28.95	43.42	57.89
ROUTED OUTFLOWS	1.23	3.19	1	76.	171.	244.	401.	509.	611.	1018.	1526.	2041.
	3.19	3.19	1	2.15	4.85	7.04	11.34	14.40	17.20	28.82	43.21	57.78

RESULTS OF VARIOUS FLOODS AT ROSEMARY LAKE DAM

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1	ELEVATION	INITIAL VALUE	SPILLWAY CHEST	TOP OF DAM
STORAGE	99.00	99.00	99.00	101.70
OUTFLOW	45.	45.	45.	91.
	0.	0.	0.	247.

247. → SPILLWAY DISCHARGE CAPACITY

RATIO OF PMF	MAXIMUM RESERVOIR ELEVATION	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.05	100.50	0.00	49.	76.	0.00	20.83	0.00
.10	101.25	0.00	83.	171.	0.00	20.17	0.00
.15	101.75	.05	92.	284.	1.83	19.50	0.00
.20	101.92	.22	95.	401.	4.33	19.00	0.00
.25	102.04	.34	98.	509.	5.83	18.83	0.00
.30	102.12	.42	99.	611.	7.00	18.83	0.00
.50	102.43	.73	105.	1018.	10.33	18.83	0.00
.75	102.81	1.11	113.	1526.	13.00	18.83	0.00
1.00	103.13	1.43	120.	2041.	14.83	18.67	0.00

→ TEST FLOOD ELEVATION

→ ROUTED TEST FLOOD OUTFLOW

	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40
H	300	5																																			
H1	5																																				
J	1																																				
J1	0																																				
K	1																																				
K1	1																																				
Y	1																																				
Y1	1																																				
Y4	99																																				
Y5	0																																				
Y4	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				
Y5	0																																				

HYDROLOGIC ANALYSIS OF ROSEMARY LAKE DAM
NATIONAL DAM SAFETY PROGRAM
NEW ENGLAND DIVISION - CORPS OF ENGINEERS

W/O N/W N/M IN MIN IDAY IHR IMIN METRC IPLT IPRT NSTAN
300 0 10 0 0 0 0 0 0 0 0
JUPEN NWT LROPT TRACE
5 0 0 0 0

MULTI-PLAN ANALYSES TO BE PERFORMED
NPLANE 1 NRTIO= 1 LRTIO= 1

NO INFLOW → RTIOS= 0.00

HYDROGRAPH-ROUTING

ROUTED OUTFLOW OF ROSEMARY LAKE

ISIAU ICOMP IECON ITAPE JPLT JPT INAME ISTAGE IAUTO
DAM-1 1 0 0 0 0 0 1 0 0

ROUTING DATA

GLUSS CLOSS AVG IRES ISAME IOPT IPMP LSTR
0.0 0.000 0.000 1 1 0 0 0

NSIPS NSTUL LAG AMSKK X TSK STORA ISPRAT
1 0 0 0.000 0.000 0.000 -102. 0

STAGE { 99.00 100.00 101.00 101.70 102.00 103.00 104.00 105.00 106.00 107.00
FLOW { 0.00 23.00 124.00 247.00 460.00 1770.00 3930.00 6930.00 10770.00 16110.00

SURFACE AREA= 0. 15. 35.
CAPACITY= 0. 45. 312.
ELEVATIONS= 90. 99. 110.

STAGE-STORAGE DATA

SPILLWAY CREST ELEVATION → 99.0

CHEL SPNU COOW EXPW ELEV COOL CANEA EXPL
99.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0

TOP OF DAM ELEVATION → 101.7
DAM DATA
TOPEL COOD EXPD DAMWIO
0.0 0.0 0.0

BREACH DATA - FAILURE BEGINS
IMMEDIATELY WITH RESERVOIR SURFACE
AT TOP OF DAM

BEGIN DAM FAILURE AT 0.00 HOURS

PEAK OUTFLOW IS 1239. AT TIME .94 HOURS

→ PEAK BREACH DISCHARGE

NORMAL DEPTH CHANNEL ROUTING

CROSS SECTION COORDINATES--STA.,ELEV.,STA.,ELEV.--ETC

STAGE-STORAGE AND
STAGE-DISCHARGE DATA
FOR THE DOWNSTREAM
CHANNEL AT THE FIRST
DAMAGE AREA

MAXIMUM STAGE IS 46.?

STREAM ELEVATION AT FIRST DAMAGE AREA

HYDROGRAPH ROUTING

SECOND DOWNSTREAM REACH

CHANNEL HUNTING REACH 2-3

ISIA0	ICOMP	LECON	ITAPE	JUPLT	JUPT	INAME	ISTAGE	LAUTO
DS-3	1	0	0	0	0	1	0	0
NULOSS	CLOSS	AVG	IMES	ISAME	IOPT	1PMP	LSTR	
0.00	0.00	0.00	1	1	0	0	0	
NSIMS	NSIDL	LAG	ANSKK	X	TSK	STORA	ISPRFT	
1	0	0	0.000	0.000	0.000	-1.	0	

UN(1) UN(2) UN(3) ELNVT ELMAA HLNTH SEL CHANNEL CHARACTERISTICS AT SECOND DOWNSTREAM DAMAGE AREA

CHINS SECTION COORDINATES--STA+ELEV+STA+ELEV--ETC
0.00 100.00 100.00 9.00 300.00 88.00 310.00 85.00 320.00 85.00 } CROSS-SECTION OF DOWNSTREAM CHANNEL
330.00 88.00 410.00 90.00 650.00 100.00 AT SECOND DAMAGE AREA

STAGE- STORAGE AND	STORAGE	0.00	-34	83	146	229	321	413	505	597	689	781	873	965	1057	1149	1241	1333	1425	1517	1609	1701	1793	1885	1977	2069	2161	2253	2345	2437	2529	2621	2713	2805	2897	2989	3081	3173	3265	3357	3449	3541	3633	3725	3817	3909	3999	4091	4183	4275	4367	4459	4551	4643	4735	4827	4919	5011	5103	5195	5287	5379	5471	5563	5655	5747	5839	5931	6023	6115	6207	6299	6391	6483	6575	6667	6759	6851	6943	7035	7127	7219	7311	7403	7495	7587	7679	7771	7863	7955	8047	8139	8231	8323	8415	8507	8599	8691	8783	8875	8967	9059	9151	9243	9335	9427	9519	9611	9703	9795	9887	9979	10071	10163	10255	10347	10439	10531	10623	10715	10807	10899	10991	11083	11175	11267	11359	11451	11543	11635	11727	11819	11911	12003	12095	12187	12279	12371	12463	12555	12647	12739	12831	12923	13015	13107	13199	13291	13383	13475	13567	13659	13751	13843	13935	14027	14119	14211	14303	14395	14487	14579	14671	14763	14855	14947	15039	15131	15223	15315	15407	15499	15591	15683	15775	15867	15959	16051	16143	16235	16327	16419	16511	16603	16695	16787	16879	16971	17063	17155	17247	17339	17431	17523	17615	17707	17799	17891	17983	18075	18167	18259	18351	18443	18535	18627	18719	18811	18903	18995	19087	19179	19271	19363	19455	19547	19639	19731	19823	19915	20007	20099	20191	20283	20375	20467	20559	20651	20743	20835	20927	21019	21111	21203	21295	21387	21479	21571	21663	21755	21847	21939	22031	22123	22215	22307	22399	22491	22583	22675	22767	22859	22951	23043	23135	23227	23319	23411	23503	23595	23687	23779	23871	23963	24055	24147	24239	24331	24423	24515	24607	24699	24791	24883	24975	25067	25159	25251	25343	25435	25527	25619	25711	25803	25895	25987	26079	26171	26263	26355	26447	26539	26631	26723	26815	26907	26999	27091	27183	27275	27367	27459	27551	27643	27735	27827	27919	28011	28103	28195	28287	28379	28471	28563	28655	28747	28839	28931	29023	29115	29207	29299	29391	29483	29575	29667	29759	29851	29943	30035	30127	30219	30311	30403	30495	30587	30679	30771	30863	30955	31047	31139	31231	31323	31415	31507	31599	31691	31783	31875	31967	32059	32151	32243	32335	32427	32519	32611	32703	32795	32887	32979	33071	33163	33255	33347	33439	33531	33623	33715	33807	33899	33991	34083	34175	34267	34359	34451	34543	34635	34727	34819	34911	35003	35095	35187	35279	35371	35463	35555	35647	35739	35831	35923	36015	36107	36199	36291	36383	36475	36567	36659	36751	36843	36935	37027	37119	37211	37303	37395	37487	37579	37671	37763	37855	37947	38039	38131	38223	38315	38407	38499	38591	38683	38775	38867	38959	39051	39143	39235	39327	39419	39511	39603	39695	39787	39879	39971	40063	40155	40247	40339	40431	40523	40615	40707	40799	40891	40983	41075	41167	41259	41351	41443	41535	41627	41719	41811	41903	41995	42087	42179	42271	42363	42455	42547	42639	42731	42823	42915	43007	43099	43191	43283	43375	43467	43559	43651	43743	43835	43927	44019	44111	44203	44295	44387	44479	44571	44663	44755	44847	44939	45031	45123	45215	45307	45399	45491	45583	45675	45767	45859	45951	46043	46135	46227	46319	46411	46503	46595	46687	46779	46871	46963	47055	47147	47239	47331	47423	47515	47607	47699	47791	47883	47975	48067	48159	48251	48343	48435	48527	48619	48711	48803	48895	48987	49079	49171	49263	49355	49447	49539	49631	49723	49815	49907	50000
STAGE- DISCHARGE	OUTFLOW	0.00	1517	5391	11830	21667	40271	73633	130893	210565	309493	3844	4459	5074	5689	6304	6919	7534	8149	8764	9379	9994	10609	11224	11839	12454	13069	13684	14299	14914	15529	16144	16759	17374	17989	18604	19219	19834	20449	21064	21679	22294	22909	23524	24139	24754	25369	25984	26599	27214	27829	28444	29059	29674	30289	30904	31519	32134	32749	33364	33979	34594	35209	35824	36439	37054	37669	38284	38899	39514	40129	40744	41359	41974	42589	43204	43819	44434	45049	45664	46279	46894	47509	48124	48739	49354	49969	50584	51199	51814	52429	53044	53659	54274	54889	55504	56119	56734	57349	57964	58579	59194	59809	60424	61039	61654	62269	62884	63499	64114	64729	65344	65959	66574	67189	67804	68419	69034	69649	70264	70879	71494	72109	72724	73339	73954	74569	75184	75799	76414	77029	77644	78259	78874	79489	80104	80719	81334	81949	82564	83179	83794	84409	85024	85639	86254	86869	87484	88099	88714	89329	89944	90559	91174	91789	92404	93019	93634	94249	94864	95479	96094	96709	97324	97939	98554	99169	99784	100399	101014	101629	102244	102859	103474	104089	104704	105319	105934	106549	107164	107779	108394	109009	109624	110239	110854	111469	112084	112699	113314	113929	114544	115159	115774	116389	117004	117619	118234	118849	119464	120079	120694	121309	121924	122539	123154	123769	124384	124999	125614	126229	126844	127459	128074	128689	129304	129919	130534	131149	131764	132379	132994	133609	134224	134839	135454	136069	136684	137299	137914	138529	139144	139759	140374	140989	141604	142219	142834	143449	144064	144679	145294	145909	146524	147139	147754	148369	148984	149599	150214	150829	151444	152059	152674	153289	153904	154519	155134	155749	156364	156979	157594	158209	158824	159439	160054	160669	161284	161899	162514	163129	163744	164359	164974	165589	166204	166819	167434	168049	168664	169279	169894	170509	171124	171739	172354	172969	173584	174199	174814	175429	176044	176659	177274	177889	178504	179119	179734	180349	180964	181579	182194	182809	183424	184039	184654	185269	185884	186499	187114	187729	188344	188959	189574	190189	190804	191419	192034	192649	193264	193879	194494	195109	195724	196339	196954	197569	198184	198799	199414	200029	200644	201259	201874	202489	203104	203719	204334	204949	205564	206179	206794	207409	208024	208639	209254	209869	210484	211099	211714	212329	212944	213559	214174	214789	215404	216019	216634	217249	217864	218479	219094	219709	220324	220939	221554	222169	222784	223399	224014	224629	225244	225859	226474	227089	227704	228319	228934	229549	230164	230779	231394	232009	232624	233239	233854	234469	235084	235699	236314	236929	237544	238159	238774	239389	240004	240619	241234	241849	242464	243079	243694	244309	244924	245539	246154	246769	247384	247999	248614	249229	249844	250459	251074	251689	252304	252919	253534	254149	254764	255379	255994	256609	257224	257839	258454	259069	259684	260299	260914	261529	262144	262759	263374	263989	264604	265219	265834	266449	267064	267679	268294	268909	269524	270139	270754	271369	271984	272599	273214	273829	274444	275059	275674	276289	276904	277519	278134	278749	279364	280000																																																																																						
DATA FOR THE 'DOWN-																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																</																			

MAXIMUM STAGE IS 90.3

→ STREAM ELEVATION AT SECOND DAMAGE AREA

THIRD DOWNSTREAM REACH → CHANNEL ROUTING REACH 3-4

ISTAU	ICOMP	IECON	ITAPE	JPLT	JPRT	INAME	ISTAGE	IAUTO
DS-4	1	0	0	0	0	1	0	0

ROUTING DATA

ULUSS	CLOSS	AVG	IHES	ISAME	LOPT	IPMP	LSTR
0.0	0.00	0.00	1	1	0	0	0

NSTPS	NSTOL	LAG	AMSKX	X	TSK	STORA	ISPRAT
1	0	0	0.000	0.000	0.000	-1.	0

NORMAL DEPTH CHANNEL ROUTING

UN(1) UN(2) UN(3) ELNVT ELMAA HLNTH SEL CHANNEL CHARACTERISTICS AT THIRD DOWNSTREAM DAMAGE AREA

CHINS SECTION COORDINATES--STA+ELEV+STA+ELEV--ETC
0.00 100.00 110.00 90.00 170.00 83.00 140.00 80.00 190.00 80.00 } CROSS-SECTION OF DOWNSTREAM CHANNEL
200.00 83.00 350.00 90.00 800.00 100.00 AT THIRD DAMAGE AREA

STORAGE	0.00	65	104	164	209	249	289	329	369	409	449	489	529	569	609	649	689	729	769	809	849	889	929	969	1009	1049	1089	1129	1169	1209	1249	1289	1329	1369	1409	1449	1489	1529	1569	1609	1649	1689	1729	1769	1809	1849	1889	1929	1969	2009	2049	2089	2129	2169	2209	2249	2289	2329	2369	2409	2449	2489	2529	2569	2609	2649	2689	2729	2769	2809	2849	2889	2929	2969	3009	3049	3089	3129	3169	3209	3249	3289	3329	3369	3409	3449	3489	3529	3569	3609	3649	3689	3729	3769	3809	3849	3889	3929	3969	4009	4049	4089	4129	4169	4209	4249	4289	4329	4369	4409	4449	4489	4529	4569	4609	4649	4689	4729	4769	4809	4849	4889	4929	4969	5009	5049	5089	5129	5169	5209	5249	5289	5329	5369	5409	5449	5489	5529	5569	5609	5649	5689	5729	5769	5809	5849	5889	5929	5969	6009	6049	6089	6129	6169	6209	6249	6289	6329	6369	6409	6449	6489	6529	6569	6609	6649	6689	6729	6769	6809	6849	6889	6929	6969	7009	7049	7089	7129	7169	7209	7249	7289	7329	7369	7409	7449	7489	7529	7569	7609	7649	7689	7729	7769	7809	7849	7889	7929	7969	8009	8049	8089	8129	8169	8209	8249	8289	8329	8369	8409	8449	8489	8529	8569	8609	8649	8689	8729	8769	8809	8849	8889	8929	8969	9009	9049	9089	9129	9169	9209	9249	9289	9329	9369	9409	9449	9489	9529	9569	9609	9649	9689	9729	9769	9809	9849	9889	9929	9969	10009
---------	------	----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	-------

MAXIMUM STAGE IS 86.6

→ STREAM ELEVATION AT THIRD DAMAGE AREA

ROSEMARY LAKE DAM BREACH OUTFLOW

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1									
ELEVATION		INITIAL VALUE		SPILLWAY CREST		TOP OF DAM			
STORAGE		101.70		99.00		101.70			
OUTFLOW		247.		0.		247.			
RATIO	MAXIMUM	MAXIMUM	MAXIMUM	DURATION	TIME OF	TIME OF	TIME OF	TIME OF	
OF	RESERVOIR	STORAGE	OUTFLOW	OVER TOP	MAX OUTFLOW	FAILURE	FAILURE	FAILURE	
PMF	DEPTH	AC-FT	CFS	HOURS	HOURS	HOURS	HOURS	HOURS	
	OVER DAM								
0.00	101.68	91.	1239.	0.00	.94	0.00	0.00	0.00	
FIRST DOWNSTREAM DAMAGE AREA → PLAN 1 STATION DS-2 → PEAK BREACH OUTFLOW									

APPENDIX E

INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS



INVENTORY OF DAMS IN THE UNITED STATES

STATE	DIVISION	COUNTY	COUNTY DIST.	NAME	LATITUDE (NORTH)	LONGITUDE (WEST)	REPORT DATE DAY MO YR
MA	1112 NED	MA 021 09		ROSEMARY LAKE DAM	4217.2	7114.4	00JAN80

POPULAR NAME	NAME OF IMPONDMENT
	ROSEMARY LAKE

REGION BASIN	RIVER OR STREAM	NEAREST DOWNSTREAM CITY - TOWN - VILLAGE	DIST FROM DAM (MI.)	POPULATION
01 06	ROSEMARY BROOK	NEEDHAM	0	29750

TYPE OF DAM	YEAR COMPLETED	PURPOSES	STRUCTURE HEIGHT (FT.)	HYDRAULIC HEAD (FT.)	IMPONDING CAPACITY (ACRES-FT.)
REOTPG	1800	R	12	12	91

DIST OWN FED R PRV/FED SCS A VER/DATE
NED N N N : N

REMARKS
STONE MAS FACE WALL , ESTIMATED CONST DATE 1920 YR BUILT EST FROM RCDS

D/S WAS	SPILLWAY	MAXIMUM DISCHARGE (CFS)	VOLUME OF DAM (CU YD)	POWER CAPACITY (MW)	INSTALLED	PROPOSED	NO.	LENGTH (FT.)	WIDTH (FT.)	LENGTH (FT.)	WIDTH (FT.)	LENGTH (FT.)	WIDTH (FT.)
1	440 U	22	247	18000									

OWNER	ENGINEERING BY	CONSTRUCTION BY
TOWN OF NEEDHAM	UNKNOWN	UNKNOWN

DESIGN	CONSTRUCTION	OPERATION	MAINTENANCE
NONE	NONE	MA DEGE	MA DEGE

INSPECTION BY	INSPECTION DATE DAY MO YR	AUTHORITY FOR INSPECTION
O'BRIEN + GERE ENGINEERS INC.	160CT79	PL 92-367

REMARKS
AUX SPILLWAY EL APPROX 1 FT HIGHER THAN SERVICE SPILLWAY

END

FILMED

8-85

DTIC